

## DP LOUKY: výsledky měření – podzim 2019

název	Z - Bpv (m n.m.)		hladina vody		vodivost μS/cm
	odměr. Bod	terén	m n.m.	m pod ter.	
V 501	230.16	230.06	227.69	2.37	456
V 502	232.9	232.23	228.80	3.43	385
V 503	238.13	237.54	235.61	<b>1.93</b>	635
V 505	248.26	247.71	234.94	12.77	977
V 508	241.38	240.68	239.44	<b>1.24</b>	289
V 511A	neměř.			3.61	887
V 486 (515)	232.34	231.89	229.32	2.57	834
V 524	234.38	233.95	229.35	4.60	493
V 526	232.67	232.13	231.98	<b>0.15</b>	388.0
HVS-1	259.96	259.76	255.86	3.90	539
V 531	230.92	230.51	229.61	<b>0.90</b>	2820
V 532	239.14	238.74	235.68	3.06	759
KL-1	264.45	264.00			sucho, dno 15.6 m p.t.
PV-10	241.24	240.96	238.51	2.45	365
PV-3	255.20	254.56			sucho, dno 8.6 m p.t.
PV-9	233.48	233.08	232.69	<b>0.39</b>	414.0
S 206	232.82	232.52	229.31	3.21	2150
St VZ1	249.85	249.70	247.95	<b>1.75</b>	417
vrt 4	262.43	262.18	248.67	13.51	516
VSV1	244.6	244.03	234.93	9.10	549
S 142	247.74	246.94			majitel nezastižen
S 143	247.11	246.66	244.54	2.12	399
S 144	254.60	254.56	253.69	<b>0.87</b>	539
S 145	246.71	246.32	243.71	2.61	361
S 149	246.16	245.63	242.50	3.13	493
S 150	244.55	244.31			majitel nezastižen
S 151	257.48	257.48	254.73	2.75	nelze odebrat vzorek
S 153	245.73	245.35	241.89	3.46	533
S 154	245.86	245.41			majitel nezastižen
S 155	246.02	246.02			majitel nezastižen
S 156	241.66	241.33	238.17	3.16	571
S 157(S-7ns)	280.68	279.84	268.26	11.58	435.0
S 159	235.56	235.26	234.07	<b>1.19</b>	428
S 160	236.38	236.13	233.74	2.39	313
S 161	236.83	236.50	233.50	3.00	397
S 163	260.13	259.90	258.86	<b>1.04</b>	366
S-155A	247.41	247.13	245.21	<b>1.92</b>	nelze odebrat vzorek
S 166	236.67	236.32			majitel nezastižen
S 167	238.62	238.52	238.37	<b>0.15</b>	nelze odebrat vzorek
S 168	245.31	244.61			majitel nezastižen
S 169	250.1	249.25	244.48	4.77	315
S 170	neměř.				majitel nezastižen
S 172	255.82	255.62	250.01	5.61	nelze odebrat vzorek
S 173	234.93	234.73			majitel nezastižen
S 175	231.45	231.33	230.38	<b>0.95</b>	283
S 176	234.52	234.42			majitel nezastižen
S 178	236.05	235.90			majitel nezastižen
S 179	236.02	236.02			majitel nezastižen
S 181	244.38	243.88	240.37	3.51	503
S 182	245.24	244.94			po rekonstrukci nepřístupná
S 183	247.94	247.65	241.85	5.80	429
S 185	244.33	244.03			majitel nezastižen
S 187	252.07	251.97			sucho, dno 3.20 m p.t.
S 188	247.59	247.49	246.65	<b>0.84</b>	294
S 190	247.83	247.63	246.68	<b>0.95</b>	327
S 191	245.94	245.59	244.10	<b>1.49</b>	753
S 194	neměř.				majitel nezastižen
S 195A	neměř.				majitel nezastižen
S 201	247.94	247.44			majitel nezastižen

## DP LOUKY: výsledky měření – podzim 2019

název	Z - Bpv (m n.m.)		hladina vody		vodivost μS/cm
	odměr. Bod	terén	m n.m.	m pod ter.	
S 202	243.42	242.77	241.70	<b>1.07</b>	309
S 205	241.51	241.06	235.04	6.02	489
S 218	259.75	259.35	250.47	8.88	405
S 220	neměř.				nepřístupná
S 263	250.03	249.68			majitel nezastižen
S 269	249.96	249.71	245.26	4.45	394
S 270	248.93	248.51	245.07	3.44	409
S 271	249.89	249.69	245.51	4.18	366
S 273	249.75	249.48			majitel nezastižen
S 274	250.22	250.14	246.22	3.92	684
S 280	254.42	254.17			sucho, dno 3.50 m p.t.
S 282	256.77	256.22	250.64	5.58	433
S-160(S-9ns)	272.55	272.25	264.72	7.53	416
V 107	249.69	249.19	245.42	3.77	313
V 109	248.93	248.43			sucho, dno 4.25 m p.t.
V 110	252.15	251.60	250.60	<b>1.00</b>	314
V 118	neměř.			3.30	311
V 122	241.15	240.65	238.43	2.37	361
V 123	248.06	247.38	238.28	2.84	416
V 108	neměř.			5.77	597
V 126	241	241.00	238.77	2.23	393
V 127	247.94	247.44	244.61	2.83	468
V 129	236.33	235.58	232.99	2.59	nelze odebrat vzorek
V 130	248.24	248.18	240.50	7.68	528.0
V 131	248.86	248.26	239.39	8.87	547
V 132	235.13	234.73	233.23	<b>1.50</b>	306
V 133	234.39	233.83	232.25	<b>1.58</b>	405
V 134	235.52	234.87	232.15	2.72	367
V 135	235.48	234.89	233.20	<b>1.69</b>	399
V 136	231.78	231.57	230.66	<b>0.91</b>	414
V 137	231.84	231.33	230.47	<b>0.86</b>	382
V 139	232.13	231.79	230.91	<b>0.88</b>	362
S 171	neměř.				dům v rekonstrukci, nepřístupná
V 507	277.56	277.06			sucho, dno 10.1 m p. t.
V 509	239.32	238.82	238.34	<b>0.48</b>	305
V 512	246.60	245.97	244.27	<b>1.70</b>	398
V 513	240.07	239.56	239.51	<b>0.05</b>	397.0
V 484 (KPV)	290.76	290.36			sucho, dno 6.43 m p.t.
V 525	235.16	234.62	231.75	2.87	546
S 285	neměř.			10.07	nelze odebrat vzorek
V 528	241.62	241.03	237.96	3.07	338
PV-14	nenalez.				nenalezen
PV-7	242.29	241.44	238.57	2.87	309
V 527	235.06	234.53	232.41	2.12	364
HV-4	275.14	274.74	254.81	19.93	671
PZ-1	246.01	245.07	242.93	2.14	325
HV-3	273.13	272.73	254.98	17.75	522.0
HVO-1	235.46	235.00	231.37	3.63	368
P-51	252.30	252.20	247.87	4.33	nelze odebrat vzorek
PVA-2	243.25	242.92	239.82	3.10	396
S KpK	258.62	258.27	253.90	4.37	496
S 189	257.94	257.64			sucho, dno 10.8 m p.t.
S 177	235.86	235.61	234.21	<b>1.40</b>	391
S 198	261.5	261.30	254.23	7.07	362
S 199	258.43	258.18			majitel nezastižen